
## **STICKING LINE** TECHNICAL SHEET

- We should be pleased to offer you this from our standard assortment.



- **Control:** Control panel is mounted to a remote pedesta
- Manual: In English
- Certifications: CE or UL, CSA

## SUPPLY

• Stations:

• Air/Electricity: 220 volt + N + ground

A compressor with air-supply of 260 litres/minute, 6 bar is needed to run the machine. Furthermore we recommend an air dryer to be mounted on the machine.

8, 12, 16 & 24 people

Empty trays are staged to the top conveyor where mechanical gates stop the tray at each work station. When a tray is removed, more are released onto the top conveyor. This provides a constant supply of product for your crew.

After sticking, the tray is placed on the bottom conveyor to be transferred to a watering conveyor and finally the greenhouse.



Storstrømsvej 55 DK - 6715 Esbjerg N Tel.: +45 7614 7676

www.ellepot.com

